

DUMPSQUEEN

HCSA-Field-Transmission & PTN V1.0

Huawei H35-260

Version Demo

Total Demo Questions: 15

Total Premium Questions: 338

Buy Premium PDF

<https://dumpsqueen.com>

support@dumpsqueen.com

dumpsqueen.com

QUESTION NO: 1

Which of the following services can be handled by the MP1 processing board?

- A. CES E1
- B. IMAE1
- C. ML-PPP
- D. Ethernet

ANSWER: A B D

QUESTION NO: 2

If an error occurs in the SDH network, the service signal recovered after the signal is decapsulated must have an error.

- A. True
- B. False

ANSWER: B

QUESTION NO: 3

When deploying ring network protection in the PTN7900 network, which items are wrong?

- A. Ring network protection and LSP APS protection can be configured at the same time
- B. The tunnel that carries the service needs to be bound to the ring network, so that the ring network can protect the service
- C. The east-west interface bandwidth of the ring network must be consistent, otherwise the ring network cannot be deployed
- D. When configuring a ring network, the east-west interfaces of the ring network can be on the same board

ANSWER: C D

QUESTION NO: 4

When PTN carries LTE services, it forwards packets based on MPLS label switching. In the MPLS label, which identification field can be used as a PTN to distinguish the label at the bottom of the stack?

- A. Label ID

- B. BS
- C. EXP
- D. TTL

ANSWER: D

QUESTION NO: 5

Which step is not included in the NE upgrade process of PTN equipment?

- A. Upgrade Feasibility Check
- B. Load the packagec. to distribute
- C. Backup after activation

ANSWER: C

QUESTION NO: 6

The U2000 network management supports a variety of external interfaces. Which of the following interfaces can be used when connecting with the network management equipment of other manufacturers?

- A. CORBA
- B. MML
- C. QX
- D. TL1

ANSWER: A

QUESTION NO: 7

In Huawei's PTN7900 LTE solution, which of the following protection methods are used in the L2VPN part?

- A. IP/VPN FRR
- B. MC-PW APS
- C. MC-LAG
- D. VPN FRR

ANSWER: B C

QUESTION NO: 8

Which of the following descriptions about the use of detection packets in the PTN LTE scheme BFD is correct?

- A. CCM message
- B. CV message
- C. FFD message
- D. Lightweight HELLO message

ANSWER: D

QUESTION NO: 9

Which of the following PTN7900-32 boards supports 10DGE ports?

- A. TPA1EXL1
- B. mA1EH1
- C. TPA1EXL2
- D. TPA1EX4

ANSWER: B

QUESTION NO: 10

Using Huawei PTN7900 to carry the L3VPN service, there is no need to plan VPN peers between the two devices

- A. Between L2/L3PTN and L3PTN at the core layer
- B. Active and standby L2/L3PTN equipment rooms
- C. Between different L2/L3PTN and L3PTN sink node pairs
- D. Between L3PTNs at the core layer

ANSWER: B C

QUESTION NO: 11

When configuring electrical layer crossing, what are the rules for time slot configuration?

- A. For the convenience of management and maintenance, it is recommended to set the time slot cutting mode to automatic mode

- B. For each board, the same time slot in the same direction cannot be used by multiple services at the same time
- C. For the same service, the time slots occupied by the receiving turbulence and the transmitting turbulence in one direction must be the same
- D. After changing the service type, there is no need to reset the service time slot

ANSWER: A B C

QUESTION NO: 12

What are the values of each wavelength in the composite signal that the spectrum analyzer is mainly used for?

- A. Optical power
- B. Signal to Noise Ratio
- C. Center wavelength
- D. Dispersion value

ANSWER: A B C

QUESTION NO: 13

When configuring SxCS board for OSN3500. Which of the following is the access capacity of a fully configured subrack?

- A. 35G
- B. 58.75G
- C. 80G
- D. 155G

ANSWER: D

QUESTION NO: 14

Which of the following options is not the reason for the R-LOS alarm?

- A. Broken fiber
- B. Excessive line attenuation
- C. The laser at the transceiver end is damaged
- D. Frame failure

ANSWER: D

QUESTION NO: 15

In the WDM transmission system, the main factors that affect the unevenness of the power balance of each channel do not include the following?

- A.** Inhomogeneity of insertion loss of each channel of the combiner/demultiplexer
- B.** The main channel adjustable optical attenuator setting is unreasonable
- C.** EDFA gain unevenness
- D.** The cable attenuation is too high

ANSWER: A B C